

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA587GL

This certificate issued to

Nicholas M. Quint
Blackhawk Aircraft Maintenance Inc.
P.O. Box 3157
Janesville, WI 53547-3157

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations. (See Aircraft Specification No. A-765 for complete certification basis)

Original Product--Type Certificate Number : A-765

Make : Raytheon Aircraft Company (Beech)

Model : D18S, E18S, G18S, H18

Description of Type Design Change:

Door handle-latch mechanism installed in forward cargo door which have been modified per STC SA995WE, only. Make modification per Aircraft Maintenance Service Instruction titled, "Beech Super 18 Cargo Door Safety Modification", dated August 24, 1981, or latter FAA Approved revisions.

Limitations and Conditions:

1. Compatibility of this design change with previously approved modifications must be determined by the installer. 2. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : August 24, 1981

Date reissued : June 4, 2004

Date of issuance : January 20, 1982

Date amended :



By direction of the Administrator

(Signature)

Gregory J. Michalik, Senior Aerospace Engineer
Airframe & Administrative Branch
Chicago Aircraft Certification Office

(Title)